



DVR-A03/DVR-103 – Writing Minimum Data

General Information:

When using the Pioneer DVR-A03 (OEM model DVR-103) DVD-Recordable drive to write a small amount of data to disc, a customer may receive the following sense code:

02-04-07 (logical unit not ready during disc closing)

This error message is for information only; the writing session closes normally for the drive and the disc. If the session shows this sense code as the only error then the disc functions properly on standard playback devices.

Details:

Pioneer recommends writing data in excess of 127.5 MB with this DVD-R/RW drive. However, data below this threshold may write without showing this sense code, depending upon the writing application.

Most writing applications also require a minimum amount of data to avoid issuing error codes but the program's data threshold could be lower than the minimum for the drive. The DVR-103 may support the lower data threshold thus withholding this sense code.

Please refer to the Pioneer website (www.Pioneer-America.com) or contact Pioneer New Media Technical Support at 310/952-2111 for additional information.